FILE NOTATIONS

Entered in NID File	Checked by Chief
Location Map Finned	Approval Letter 12-12-69
Card Indexed	Disapproval Letter
COMPLETION DATA:	
Date Well Completed 13-24-69	Location Inspected
W WW TA	Bond released
GW OS PA	State or Fee Land
LOGS F	ILED
Driller's Log	
Electric Logs (No.)	
E I Dual I Lat	GR-N Micro
BHC Sonic GR Lat	그런 그는 바람이 이 살살을 하는 그 것이다. 그는 네트를 하는 것은 그 것이라는 그는 것이다.
CBLog CCLog Othe	이 없는 사람들이 다른 사람들이 가는 사람들이 가지 않는 것이 되었다. 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
나는 경기 회원 회원 그는 학생들은 그 나는 지수 있는 것 같아. 그는 것 같은 것은 그는 학생	그러움 방문 가능이다.

49 ger

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:


UNITED STATES SUBMIT IN TALLICATE (Other instruments on reverse side)

Form approved. Budget Bureau No. 42-R1425.

	DEPARTMENT	OF THE I	NTERIOR		5. LEASE DESIGNATION	N AND SERIAL NO.
	GEOLOG	SICAL SURV	EY		U-02622	2
APPLICATION	FOR PERMIT T	O DRILL, L	DEEPEN, OR PLUG E	BACK	6. IF INDIAN, ALLOTTI	EE OR TRIBE NAME
1a. TYPE OF WORK					7. UNIT AGREEMENT	NAME .
b. TYPE OF WELL	LL X	DEEPEN [PLUG BA	CK 🗀	. UNIT AGREEMENT	name.
OIL GA	S COTHER		SINGLE MULTIP	PLE	8. FARM OR LEASE NA	AME
2. NAME OF OPERATOR			20112		Lingelba	ch
·	buff - H. P. I	McLish			9. WELL NO.	
3. ADDRESS OF OPERATOR	an Budlalana I	Banuar Co	olorado 80202		10, FIELD AND POOL,	
	on Building, I		th any State requirements.*)		Horseshoe	-01
	sl x 660 fel		 ,		11. SEC., T., R., M., OR	BLK.
At proposed prod. zone		· · · · · · · · · · · · · · · · · · ·	وموالا يستدانها		AND SURVEY OR A	REA
			SENE	SE	20-T68-R21E	
14. DISTANCE IN MILES A		EST TOWN OR POS	T OFFICE*	•	12. COUNTY OR PARISI	1
15. DISTANCE FROM PROPOS	O miles North		16. NO. OF ACRES IN LEASE	1 17 NO. 6	Uintah OF ACRES ASSIGNED	Utah
LOCATION TO NEAREST PROPERTY OR LEASE LI		660'	1462.70		HIS WELL 640	
(Also to nearest drlg. 18. DISTANCE FROM PROPO	unit line, if any)	000	19. PROPOSED DEPTH	20. ROTA	RY OR CABLE TOOLS	
TO NEAREST WELL, DR OR APPLIED FOR, ON THIS	ILLING, COMPLETED,	4000'	3800' Winte		Rotary	
21. ELEVATIONS (Show whether	ther DF, RT, GR, etc.)		<u> </u>	•	22. APPROX. DATE W	ORK WILL START*
4721 GF	<u> </u>		· ·	<u> </u>		- \$4 - \$1
23.	PI	ROPOSED CASIN	NG AND CEMENTING PROGR.	AM		i Kr
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FO	OOT SETTING DEPTH		QUANTITY OF CEME	INT
12 1/4"	8 5/8"	24#	250'		150 sacks (c	ire.) 🗸
7 7/8"	4 1/2"	9.5#	3800' 🗸		200 "	
Nipple up Scha 3800' maintain sands below a depth. If ind as well. "An excep 4000' from the currently comp	iffer double hy ing proper mudepth of 3000 licated to be position to Rule (Luff-McLish (pleted as a Uin	ydrolic M d weight t '. Check productive C3(b) is t #1 Joyce I ntah form	' and set 250' of OP and test same.' To protect against BOP on each tour. I want of the second of th	Drill 1700 Run /2" cas locat	7 7/8" hole pai gas mear IES log at ting and compand compand to as it is 1, T6S, R2LE	to ing otal lete about
the proposed w	rell are control PROPOSED PROGRAM: If portional rill or deepen directional	olled by 1 roposal is to deep	cal conditions and the applicant." en or plug back, give data on plug data on subsurface locations and the conditions are considered. Operator	resent prod	uctive zone and propos	ed new productive
	ol or State office year	77				
(This space for Federa	at the State Office 11861					
	047-30072			**		

PROJECT

T6S, R2IE, SLB&M



X = Corners Located (Brass Caps)

KENNETH D. LUFF

WELL LOCATION AS SHOWN IN THE NEW SEI/4, SECTION 20, T6S, R2IE, SLB&M. UINTAH COUNTY, UTAH.

CERTIFICATE

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM
FIELD NOTES OF ACTUAL SURVEYS MADE BY ME OR UNDER MY
SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE
BEST OF MY KNOWLEDGE AND BELIEF.

Sene Stewart

REGISTERED LAND SURVEYOR REGISTRATION Nº 3154
STATE OF UTAH

UINTAH ENGINEERING & LAND SURVEYING
POBOX Q ~ 110 EAST - FIRST SOUTH
VERNAL. UTAH - 84078

SCALE " = 1000'	DATE Dec. 1969
PARTY LDT & KM	REFERENCES GLO Township Plat
WEATHER Clear & Cold	K.D. LUFF

December 12, 1969

K.D. Luff & H.P. McLish 210 Patterson Building Denver, Colorado 80202

> Re: Well No's: G.I.C. Federal #1, Sec. 33, T. 6 S, R. 21 E, Lingelbach Federal #3, Sec. 20, T. 6 S, R. 21 E, Uintah County, Utah

Gentlemen:

Insofar as this office is concerned, approval to drill the above mentioned wells is hereby granted. However, this approval is conditional upon this office receiving a surveyor's plat for the G.I.C. Federal #1 well. The approval is granted in accordance with Rule C-3(c).

Should you determine that it will be necessary to plug and abandon this well, you are hereby requested to immediately notify the following:

PAUL W. BURCHELL - Chief Petroleum Engineer HOME: 277-2890 OFFICE: 328-5771

This approval terminates within 90 days if the wells have not been spudded-in within said period.

Enclosed please find Form OGC-8-X, which is to be completed whether or not water sands (aquifers) are encountered during drilling. Your coe operation with respect to completing this form will be greatly appreciated.

K.D. Luff & H.P. Lish December 12, 196 Page 2

The APT numbers assigned to these wells are: 43-047-30072-Lingelbach #3, 43-047-30073-G.I.C. Federal #1, (see Bulletin D-12 published by the American Petroleum Institute).

Very truly yours,
DIVISION OF OIL 8 GAS CONSERVATION

CLEON B. FEIGHT DIRECTOR

CBF:sd Enclosures

cc: U.S. Geological Survey 8416 Federal Building Salt Lake City, Utah 84111

A Company of the Comp Hen Taff - Horspoont thil Denglibrah = # 3 NESE 20, 65 2/E

Wentak from who 2000 99

50 als prof. - pall 2000 99 42

35 25 ly gratub - 33 2 be

Of sufe pop (# 2)

65 7/E (3) Lingblock # 2 - SE 5 /= m30 GS 2/E alme 3 mel P+ 1 10/3/70 by U.S. & S. - Jerry Donich - PMB

POOR GOPY

UNITED STATES

SUBMIT IN DUPLICATE*

(See other instructions on reverse side)

SUBMIT IN DUPLICATE*

Form approved.

Budget Bureau No. 42-R855.5.

5. LEASE DESIGNATION AND SERIAL NO.

)EP/	\RT	ME	NT	OF	THE	INT	ŒRI
				A 40 To 1	SHR	2	

Form a	nnroved.			
701	6	ÀT.	40	DARE
Form a Budget	Bureau .	LVO.	44	- rtooo.o

\mathcal{A}	GEO	DLOGICAL S	URVEY				U-02622	2
WELL CO	OMPLETION OF	R RECOMPLI	ETION I	REPORT	AND LO	G* 6	. IF INDIAN, ALLO	TTER OR TRIBE N
ia. TYPE OF WE	CLL: OIL WELL	GAS K	DRY 🗌	Other		7	. UNIT ACREEMEN	T NAME
b. TYPE OF CO								
NEW X	WORK DEEP-	BACK I	DIFF DESVR.	Other		8	. FARM OR LEASE	
2. NAME OF OPER	ATOR						Lingelb	ech
Kenneth						9	. WELL NO.	
	erson Buildin	o Benver	Colors	do 80	202	10	O. FIELD AND POO	L, OR WILDCAT
4. LOCATION OF W	ELL (Report location cle	arly and in accorda	nce with an	y State requ			Horseshoe	Dend :
At surface	1527 fsl x 66	0 fel (NE	E)			1	1. SEC., T., R. M.,	OR BLOCK AND SUR
At top prod. in	nterval reported below							
At total depth							20-76S-R2	AE .
		14.	PERMIT NO.		DATE ISSUED	1:	2. COUNTY OR	13. STATE
	الويوسي والمنافض والمالان						Uthtah	Oten
5. DATE SPUDDED	16. DATE T.D. REACH	ED 17. DATE COMP	L. (Ready t	1 -	8. ELEVATIONS (1		24, 41-C.)	CLEV. CASINGHEAD
12/17/69	12/24/69		00 a. v		4721 Grd.		ROTARY TOOLS	CABLE TOOLS
). TOTAL DEPTH, MI	a TVD 21. PLUG, BAC	IK T.D., MD & TVD	HOW M	TIPLE COMPI ANY*		LLED BY	TOTARY TOOLS	EARIN TOOLS
3801	ERVAL(S), OF THIS COMI	LETION-TOP. BOTTO	M. NAME (I	(D AND TVD)		->	25	
								SURVEY MADE
								20
, TYPE BLECTRIC	AND OTHER LOGS RUN				7		27. w	AS WELL CORED
ldirita L	ogging Co., S	chlumberre	r IES I	og and	GRM Log			No.
					ga set in well)			
CASING SIZE	WEIGHT, LB./FT.	DEPTH SET (MD)	نسست فالسند	LE SIZE		MENTING REC		AMOUNT PULLE
8 5/8"	24#	225'	_ 12	1/4"		5 sacki		
4 1/2"	9.5#	3798	_ 7	7/8"	20	O sacks		
			_					
	LINE	R RECORD			30.	TUE	ING RECORD	10
SIZE	TOP (MD) BOT	TOM (MD) SACKS	CEMENT*	SCREEN (1	MD) SIZE	DEP	TH SET (MD)	PACKER SET (M
		48			2 3/	8"	16DL	3691
	scorp (Interval, size an terval-1/2" a			32.	ACID, SHOT	, FRACTURI	e, cement squi	EEZE, ETC.
	458-69, 3512-		3		TERVAL (MD)	7 AL - AL	T AND KIND OF M	
	582-83, 3586-			3422-	305A	500 gr		
625-30						10,00	3# 10/20 (- Allendaria
						See a	ttached re	mant
			PROI	DUCTION		, oce a		
TE FIRST PRODUC	TION PRODUCTION	N METHOD (Flowing			and type of pur	np)		s (Producing or
Temp. Sus	p.	Flowing					shut-in)	Suop.
ATE OF TEST	HOURS TESTED		D'N. FOR	OIL—BBL.	.GAS—M			GAS-OIL BATIO
3/9/70	24	1"			43		86~508	
ow. Tubing Press.		CALCULATED OIL 24-HOUR RATE	—BBL.		-MCF.	WATER—BBI	at the first of the second	RAYITY-API (CORR.
175	GAS (Sold, used for fuel,	vented etc)			439	86-5		
	and those, more los lucis	20.,,				11	J. Tadle	
Flare 5. LIST OF ATTACE	HMENTS					1		
	Report and I	.ogs						
. I hereby certif	y that the foregoing and	attached informat	ion is comp	lete and cor	rect as determin	ed from all	available records	
	/ //	1 /1			O			3/19/70
SIGNED	MAH	deft	TITLE		Operator	1 1	DATE	M 73/ / A

NSTRUCTIONS

If not filed prior to the time this summary record is submitted, copies of all currently available logs (drillers, geologists, sample and core analysis, all types electric, etc.), formation and pressure tests, and directional surveys, should be attached hereto, to the extent required by applicable Rederal and/or State laws and regulations. All attachments will be issued by, or may be obtained from, the local Federal types of lands and leases to either a Federal agency Any necessary special instructions concerning the use of this form and the , particularly with regard to local, area, or regional procedures and practices, either are shown below well completion report and log on all See instructions on items 22 and 24, and 33, below regarding separate reports for or both, pursuant to applicable Federal and/or State laws and regulations. and/or State office.

should be listed on this form, see item 35.

tem 4: If there are no applicable State requirements, locations on Rederal or Indian land or Federal office for specific instructions.

show the producing Submit a separate report (page) on this form, adequately identified (where not otherwise shown) for depth measurements given in other spaces on this form and in any attachments. in item 24 tems 22 and 24: If this well is completed for separate production from more than one interval zone (multiple completion); so state in item 22, and the additional data pertinent to such interval (if any) for only the interval reported in item 33. produced, showing Indicate which elevation is used as reference), bottom(s) and name(s) or each additional interval to be separately interval, or intervals, top(s) tem 18:

Consult local State

should be described in accordance with Federal requirements.

should show the details of any multiple stage cementing and the location of the cementing tool. (See instruction for items 22 and 24 above. interval to be separately produced fem 29: "Sacks Cement": Attached supplemental records for this we fem 33: Submit a separate completion report on this form for each

	A	TRUE VERT. DEPTH		(+1334)																
	TOP	MEAS. DEPTH	3236	3398	3506	3608	ms.3749													
		NAME	"A" Marker	"B" Marker	"C" Marker	"D" Marker	Green River Trans													
						2. 0	<u> </u>							10. 10. 10. 10.	8.9.	5		1	i si	=
								ن نوچ پ								47				學打了 人名丁科人
COVERIBE	ETC.																			
, AND RE	NTENTS,																*		r	4
AND SHUT-IN PRESSURES, AND RECOVERIES	DESCRIPTION, CONTENTS, ETC.												क े के							
					-					Y.,		Y.								
N, PLOWI																				
D, TIME TOOL OPE.	воттом								C REPORT											
DEPTH INTERVAL TESTED, CUSHION USED, TIME TOOL OPEN, BLOWING	TOP								SEE GEOLOGIC REPORT											
PTH INTERVAL	FORMATION																			

WELL SUMMARY

Operator:

Kenneth D. Luff

Well:

#3 Lingelbach

Location:

NE SE (660 fel x 1527 fsl) Section 20, T6S, R21E

Uintah County, Utah

Elevation:

4721 Grd 4732 KB

Contractor:

Barker Drilling Service

Rig Type:

Ideco (Bowden)

Commenced:

December 17, 1969

Completed

December 24, 1969

Total Depth:

3798 Schlumberger 3801 Driller

Casing:

8 jts. of 8 5/8", 24#, J-55 casing, landed Surface:

at 225' KB - cemented with 165 sacks of

regular cement with 2% calcium chloride

Production:

121 joints of 4 1/2#, 9 1/2#, J-55, landed @ 3798' KB, cemented with 200.

sacks of 50/50 pozmix.

Hole Size:

12 1/4" to 228'; 7 7/8" to 3801'

DST:

None

Logging Services:

Aldirita Logging Company 3420 to 3801

Schlumberger IES Log 227 to 3798'

Schlumberger GRN Log 3100 to 3772'

Samples:

Vernal Warehouse

Geologist:

Al Chatham - Kenneth D. Luff

Status:

Attempt Uinta gas sand completion

CHRONOLOGIC HISTORY OF WELL

- 12/16/69 Moving in Barker Ideco rig and rigging up same.
- 12/17/69 Completed rigging up. Started mixing mud at 6 p.m. and spudded 12 1/4" surface hole at 9:45 p.m. Drilled ahead to 122'. Survey 1/2 degree @ 90'.

Total Footage 122'

12/18/69 - Drilled 12 1/4" surface hole to 228'. Ran 8 joints of 8 5/8" surface casing, 8 Rd, 24#, STC, landed at 225.34 KB and cemented with 165 sacks of type G regular cement with 3% calcium chloride. Plug down @ 7:15 a.m. Had good circulation throughout job. W.O.C. and nippling up from 7:15 a.m. to 6:30 p.m. Drilling cement and plug at 6:30 and new hole at 8 p.m. Drilled 7 7/8" hole to 707'.

Total Footage 479'

- 12/19/69 Drilled 7 7/8" hole to 1965' with water. Made trip for bit #2 @ 1139 and for bit #3 at 1774'.

 Total Footage 1258'
- 12/20/69 Drilled 7 7/8" hole to 2910' with water. Made trip for bit #4 @ 2278'. Cleaned pits on trip. Laid down one joint of drill pipe on trip due to hole in pipe.

 Total Footage 945'
- 12/21/69 Drilled 7 7/8" hole to 3482' with mud. Made trip for bit #5 at 2862. Cleaned pits and started mudding up at 3300'.

 Made trip for bit #6 @ 3482'. Mixed 55 sacks of Bar @ 3482' to control hydrostatic for gas zone @ 3360'..

 Total Footage 572'
- 12/22/69 Drilled 7 7/8" hole with mud to 3706'. Completed trip for bit #6. Made trip for bit #7 @ 3507 after bit would not drill. Wash 30' to bottom on trip @ 3507'.

 Total Footage 224'
- 12/23/69 Drilled 7 7/8" hole to 3801' with mud. Made trip for bit #8 @ 3706'. Reamed 20' on trip at 3801'. Made 10 stand short trip and circulated one hour before coming out to log hole. Ran Schlumberger IES Log. Went back in hole to lay down drill pipe.

 Total Footage 95'
- 12/24/69 Laid down drill pipe and collars. Ran 12l joints of 4 1/2", 9 1/2#, J-55 production casing, landed at 3798' KB. Cemented with 200 sacks of 50/50 posmix 2% gel and 10% salt with plug down @ 8:45 a.m. Circulated 45 minutes before cementing pipe had good circulation throughout job. Float would not hold so left 400# on pipe. Tore down and released rig.

^{*}Ran scratchers over following zones: 3460-75, 3490-3500, 3505-20, 3550-3600, 3615-35, 3665-3700, 3720-35.

Luff #3 Lingelbach NE SE Sec. 20, T6S, R21E Uintah County, Utah

12/31/69 - Rigged up Schlumberger and ran Gamma Ray Neutron Log. Perforated as follows:

3462-63 - 2 holes 3468-69 - 2 holes 3512-13 - 2 holes 3552-53 - 2 holes 3572-76 - 2 holes 3582-83 - 2 holes 3588-89 - 2 holes 3617-18 - 2 holes 3625-30 - 4 holes

Went in hole with 110 jts. of 2 3/8" tubing. Landed at 3441'. Hooked up well head. Unable to close master valve due to ice in valve. Shut down.

- 1/1/70 Replaced master gate. Ran swab from 3400'. Well unloaded immediately. After 2 hrs. of flow, well still making considerable water from casing. Gas in excess of 1 million CFG/D per day. Shut well in at 6:30. Will clean up well tomorrow.
- Shut in pressures CP-1050# TP-1050#. Open well to pit @ 7:00 a.m. on 3/4" choke and leave well open remainder of day. At 6:00 p.m. CP-200# TP-50#. Well producing gas @ 1,100 MCF/D with heavy fog of water. Shut well in.
- 1/3 Well shut in.
- TP-1500# CP-1500#. Open well to pit and blow down in 5 min.

 TP-"0" CP-50#. After 30 min. well producing at rate of TSTM.

 Shut well in.

 8:00 P.M. TP-1500 CP-1470. Open well to pit and blow down in about 5 min., heavy fog of water. TP-50# CP-175#. No measurement of gas. Shut well in.
- 1/5 Shut in pressure TP-1450# CP-1480#.
 9:30 a.m. Open well to pit and blow down in 5 min.
 10:00 a.m. TP-100# CP-220# 542 MCF/Day Mist of water
 1:40 p.m. TP-100# CP-140# 729 MCF/Day less water
 2:40 p.m. TP-100# CP-140# 754 MCF/Day less water
 10:30 p.m. TP-100# CP-140# 777 MCF/Day shut in well
 11:50 p.m. TP ? CP-1220#
- 1/6 Well shut in.
- Shut in pressure TP-1450# CP-1470#. Blow down in 5 to 7 min. No blow. No test. Shut in.

Luff #3 Lingelbach NE SE Sec. 20, T6S, R21E Uintah County, Utah

- Shut in pressure - TP-1450# - CP-1470#. Well blew down in 5 1/8 min. Well making good stream of water (1/4" to 3/8" stream). Frac Uintah sand perf above with 10,000 #10-20 sand in 8,000 gallons Potassium chloride water. Spearhead frac with 500 gallons 15% acid. At 10 BPM, noted formation break from 2400# to 2000#. Dropped 5 RCN balls and noted decline in injection rate from 23 BPM to 13 BPM @ 3500#. Average injection rate 16 BPM. Average pressure 3500#. Instant SIP-1700#, 15 min. SIP-1200#. Total load 308 bbls. Job complete @ 11:45 a.m.

3:45 p.m. - TP-300 - CP-240#. Open well to pit thru casing.

4:25 p.m. - First show of gas in water. Still unloading to pit thru annulus. Blow increasing.

5:00 p.m. - Blow increasing. Heavy stream water. (25' to 30')

5:20 p.m. - Shut casing and open tubing. Well about same as 5:00.

5:30 p.m. - Tubing unloaded and open both tubing and casing, heavy water both sides.

5:45 p.m. - Water and gas appears to be decreasing? Smell of acid gas. Casing making the most water.

6:00 p.m. - Tubing and annulus blowing heavy water.

9:00 p.m. - Tubing and annulus blowing heavy water. Not too much gas. Shut well in.

- Shut in TP-1475# CP-1475#. Open well with heavy spray of 1/9 water @ 8:30 a.m. 1:35 p.m. - TP-125# - CP-660# - 2,530 MCF-est. 40 BWPD
- Shut in TP-1475# CP-1475#. Open well with spray of water 1/10 @ 9:00 a.m. 10:00 a.m. - TP-100# - CP-800#. 0 to 2.3 MMCF/D - Flow by heads, maybe less water. 4:00 p.m. - TP-125# - CP-660# - 2.3 MMCF/D - less water than on1/9/70. Flow rate better. Stabilized, however, too much water to efficiently produce.

4:05 p.m. - CP to 875#.

- 1/24/70 Rig up Colorado Well Service. Mix 140 bbls. of 10.2#/gal. calcium chloride water. Kill well with 115 bbls. of water. Well died. Nipple up BOP and shut down for overnight.
- 1/25/70 Open tubing with large head of gas. No pressures. Well unloaded water and gas out of tubing. Shut well in. Mixed calcium chloride Shut down for overnight. water.
- 1/26/70 Blew well down. Killed well with 100 bbls. calcium chloride water. Pulled tubing. Re-ran tubing with Baker tension packer. Set packer at 3601 KB. Packer bull plugged on bottom. Perf. nipple on top of packer. Well taking water continuously while running in tubing. Total calcium chloride water pumped into well 275 bbls. Removed BOP. Put on well head. Leave well open for three hours. Did not flow. Shut in overnight.

Luff #3 Lingelbach NE SE Sec. 20, T6S, R21E Uintah County, Utah

- 1/27/70 Well flowing to atmosphere. At 3:45 p.m. tubing pressure 140, casing pressure 460. Rate 1790 MCF. Heavy spray of water with pencil stream running from pipe. Continue to blow well to atmosphere.
- 1/28/70 Well open to atmosphere overnight. 7:15 a.m. tubing pressure 125, casing pressure 425. Rate 1790 MCF. Possibly slightly less water, however, spray heavy. Pencil stream still running from flow line. 8:00 p.m. tubing pressure 110, casing pressure 400. Rate 1630 MCF. Spray of water still heavy. Pencil stream still running from flow line. Volume of water still approximately the same as prior to setting packer. Very little change in water. Well does not look too good at the present time.

LITHOLOGY

Refer to lithologic descriptions shown on mud logger report and log of well.

SIGNIFICANT MUD LOGGER SHOWS

Sand Interval 3461-64 & 3467-70	Net (2) (2)	Comments Total gas readings 600 units; all methane. Mud weight 9.2 lbs./gal. (Gas Productive)
3509 -1 4	(4)	Total gas reading 20 units; dominantly methane with trace ethane. Mud weight 9.8#/gal. (Possible gas productive)
3550-57	(6)	Total gas reading 85 units; dominantly methane with trace ethane. Mud weight 9.8#/gal. (Possible gas productive)
3570 - 76	(4)	Total gas reading 25 units; dominantly methane with trace ethane. Mud weight 9.8#/gal. (Possible gas productive)
3581-84	(2)	Total gas readings 40 units; all methane. Mud weight 9.9#/gal. (Possible gas productive)
3586-90	(4)	Total gas readings 55 units; all methane. Mud weight 9.9#/gal. (Possible gas productive)
3615-19	(2)	Total gas readings 20 units; all methane. Mud weight 9.9#/gal. (Possible gas productive)
3624-30	(5)	Total gas readings 180 units; dominantly methane with trace ethane. Mud weight 9.8#/gal. (Possible gas productive)
3666-75	(5).	Total gas readings 90 units; dominantly methane with trace ethane and propane. Mud weight 9.8#/gal. (Possible gas productive)
3688 - 97	(7)	Total gas readings 100 units; dominantly methane with trace ethane and propane. Mud weight 9.8#/gal. (Possible gas productive)
3720-24	(3)	Total gas readings 10 units; all methane. Mud weight 9.8#/gal. (Probably tight gas zone)

K. D. Luff Lingelback # 3 Production Test

RECEIVED MAR 17 1970

2-25-70 M.I. separator w/Casada and start r.u. for flow test
2-28-70 Unload well to air. SIPC 1490 psi SIPT 1300 unload large head water. S.I.
well wait on transportation.

3- 1-70 SIPT 1350 SIPC 1490 unload well to air, lay water line w.o. methanol for separator to start test.

3- 3-70 SIPC 1500 SIPT 1300, finish tie in on separator, unload well to air, turn well through separator for extended flow test.

	Time	Thg.	Csg.	Back Pressure	Remarks
	9:40 A.	M. 1200	1475	390 p.si	Open well at flow rate 750 MCF/D.
	10:00 A.	M. 600	950	340 p.s.i.	Gas rate 620 MCF/D water rate 340 B.W.P.D.
	4:00 P.	M. 200	550	125 p.s.i.	Gas rate 500 MCF/D water rate 175 to 340 BWPD
	5:00 P.	M. 175	525	140 p.s.i.	Gas rate 500 MCF/D water rate 175 to 340 BWPD
3-4-70	7:00 A.	M. 200	525	140 p.s.i.	Gas rate 517 MCF/D water 85 to 257 BWPD
	5:00 P.	м. 200	520	140 p.s.i.	Gas rate 517 MCF/D water 85 to 171 BWPD
3- 5-70	12:10 P.	M. 200	500	150 p.s.i.	Gas rate 517 MCF/D water 18 to 340 BWPD
	1:00 P.	м. 200	500	150 p.s.i.	Gas rate 517 MCF/D water 18 to 340 BWPD
3- 6-70	4:15 P.	M. 200	500	150 p.s.i.	Gas rate 481 MCF/D water 96 to 168 BWPD
3 - 7- 70	2:40 P.	м. 150	500	130 p.s.i.	Gas rate 458 MCF/D water 86 to 340 BWPD
3- 8-70	1:45 P.	M. 200	500	150 p.s.i.	Gas rate 537 MCF/D water low rate 86 BWPD, heads are less
					frequent but over all rate is greater than 100 bbls. per day
3- 9- 70	5:20 P.	M. 175	475	150 p.s.i.	Well is heading w/gas rate and water rate erratic gas rate 439
, ,					MCF/D, water rate low 86 BWPD high rate 508 BWPD. Estimated
					cumulative water this test is 1050 bbls. w/est. gas cumulative 3,450 MCF.

FORMATION TOPS

Uin <u>ta</u>	Surface
"A" Marker	3236
"B" Marker	3398 (+1334)
"C" Marker	3506
"D" Marker	3608
Green River Trans.	3749

MIDNIGHT DRILLING DEPTHS

Date	<u>Depth</u>	<u>Footage</u>
$1.2\overline{/17/69}$	122	122
12/18/69	707	614
12/19/69	1965	1258
12/20/69	2910	945
12/21/69	3482	572
12/22/69	3706	324
12/23/69	3801	95
12/24/69	3801	

DEVIATION SURVEYS

Depth	Deviation	Pump Press.	Weight	<u>RPM</u>
90'	1/2 degree		-Water	
228'	3/4 degree	•	TT ,	•
1139'	3/4 degree	•	11	
1774'	l degree		π - *	,
2862 *	l 1/2 degree		TT .	
3351'	3/4 degree	600-700	40,000	80

BIT RECORD

No.	Size	Make	Type	<u>In</u>	<u>Out</u>	Footage	Hours
1	7 7/8	HTC	osc3J	238	1139	901	$10 \ 1/2$
2	7 7/8	HTC	OSC3J	1139	1774	635	11 1/4
. 3	7 7/8	Reid	YT3-TJ	1774	2278	504	12 1/4
Ц.	7 7/8	Smith	DTTJ	2278	2862	584	13 1/2
5	7 7/8	Smith	DTTJ	2862 '	3482	620	15 3/4
6	7 7/8	Smith	RB5J	3482	3510	28	Lţ.
7	7 7/8	Reid	YTITJ	3510	3711.	201	13
8	7 7/8	Smith	RB5JS	3711	3801	90	12 1/4

DAILY MUD CHARACTERISTICS

Note: Clear water was used as a drilling fluid to a depth of 3100' at which time a chem-gel mud was mixed. The well was serviced by Baroid.

Date	Depth	Type	Weight	Visc	W.L.	PH	<u>% Sd.</u>
12/21/69	3408	Chem-gel	9.2	40	15	9.5	1/10
12/22/69	3560	Chem-gel	9.8	43	9.4	10.0	1/2
12/23/69	3801	Chem-gel	10.1	50	9.4	10.5	1/2
14/63/03		- 0			*		

and the legities Company LEGENO Sand Silisione [====-] 265-8164 3901 TRUMBLE S.E. ALBUQUERQUE, NEW MEXICO PHONE 298-7581 Chert Shale DADA Coal Limestone Depth Longad Company ___KENNETH D. LUFF IIII Icheous Delomita KKKR! From 3420' To 3800' Well # 3 LINGELBACH Anhydrite 1111 Date Logged Location SEC. 20, T68, R21E, Calibration Chromategraph _ From _____ To - Particaa County HINTAE - Butanes Elov. G. L.____K. 8.__ State UTAH - Elbana Rad Typo CHEN-GEL - Mathena : Cuffings Gos Drill Rote - Min. / Ft. Lithology Depth Description Mud Gas 발1.- VIS.-KL.-F.C.- Ph.-CL. 500 SAMPLE QUALITY POOR SS, WHT LT GY VF-FG TITE TO SM V/FRI SF CEM CALC SM S & P S SL GLAUC FRI TO SM UNCON HVY TR BENT SH, VARI COLOR BRITE GN-GN RD BN MOTT SM SLTY SNOY DOLO'C TO LIMEY FIRM TO WXY LS, BN VFX HD DNS SH, RD BN LT GN-GN -GY YELL MORT FIRM FN TEXT TO SLTY SND SM SFT FXY SM LIMEY FN MICA SS, WHI LT DERTY GY VFG TITE/CALC CEM SS WHILL CLI LT GY VILF G TITE TO SH CALC CEN FREE SE CLAUC

LHARM ALDIRITA LOQUING Company Sand THANKI Silfstone 265-8164 3901 TRUMBLE S.E. ALBUQUERQUE, NEW MEXICO

PHONE 203-8104
203-8104 Shale Chart FEETE Cod Limestana Dopin Leggsd KSSE 77777/ Igneous Delotaire Company KENNETH D. LUFF From To Anhydrite 1777 # 3 LINGELBACH Mall _____ Date Logged Calibration Chromatograph Location - Pantona COUNTY ____ Elev. G.L. Martin K. D. Stete____ - Effects Mud Typo..... Cut Cuttings Gas Deceription Mud Gas Drill Rato - Min. / Ft. Lithology Depth 54321 Wt.- Via.-WL.-F.C.-Ph.-CI. SS, WHT LT UY YF-FG TITE TO SM CL FRI T UNCON TR GLAUC BIOT SS, A/A SM Y/FRI CAL CÉM SM UNCON TR STN SH. LT BRITE GN-GN. RD BN MOTT YELL TR LT GY PIRM SLTY TO SNOY TO V SFT WXY W/LMBED SD GRS LIME I.P. MYY TR FURP SH SS, WHT LT GY GN/VE-FG PRED V/FRI SL TR STE NO PHYO SUB AND TO SUB RND SM W/ IMBED LS NOUGLES S. WHY LY GY CL TR

LEGEND ALDINIA Logging Congany ভিন্ন Silistone Sand 265-8164 Shola Chert 10000 3901 TRUMBLE S.E. ALBUQUERQUE, New Mexico PHONE 298-7581 FEET Cod Limestone Doppin Logged W/Z/ZZ Ignsous Kake Dolomite KEMNETH D. LUFF Company ____ From Livering TO was a service of the service of th 17777 Anhydrite Wall ____ - 集 3 LINGELBACH Data Lagged Calibration Chromolograph Location _____ - 5 ------ Penisno -County _____ Elov. G. L. Landers N. B. Carrelle 1994 Typo. Cut Cutilingo Gas Mud Gos Description Drill Rote - Mia. / Ft. Depth Lithelogy 54321 WI- VID-WIL-F.C. - Ph.- CL. SH. LT GN∕GN SFT WXX w/sh rd bn mott yeld TR PURP FN TEXT FIRE TO SLTY SNOY FN MIC S. WHT'CL LT BN CL WYG HD TITE TO SM S TRI CALC CEM SM S&P S. A/A E/SM WHI CL TUNCON SS TR LG CTZ SUB-ANG TO SUB RND Y/SL TR STN NO FLUO SL TR GLAUC BIOT SU, WARI COLOR LT GN GN BRITE ON ROBIN MAR PURP MOTT FIRM TO VISTINAY SNOY SHITY I.P. SM LIMEY SS. WHT LT DINTY GY YI'G TITE S. WHT LT GY SM S&F LT BN SFT CEN TO FRI BVY TR STN NO VARI UGLOR ROGE.

Sond -[FFFFF] Shedons Shola FEFEE Chart 9901 TRUMBLE S.E. ALBUQUERQUE, New Mexico Phone 298-7581 TAGA [[[(00]) Lingstone Company KENNEYER D. LUFF Ocpin Logged Delocuite [222222] . lgaqqqua The constant of the contract of the contract of the constant of the contract o Anhydrite 17777 Vall # 3 Lingelbach Data Lingged Location Calibration Chromatograph County Silv. G. L. Common. N. B. Common. State ____ SALE TYPE MARKET AND A THE ADMINISTRATION OF THE PARTY OF Curl Currings: Gas Drill Rule - Ma. / Ft. Death Lithelogy Deportation Mud Gos 54321 With Vistrik L. - F.C. - Ph. - GI. SS, WHT LT GY FG TITE TO, SN SFT CEM. SR. VARI COLOR LT ON GN BD BN.TH GY MOTT YELL FURP FN TEXT FIRM TO SET WXY SS, SHT LT CY TR LT CH LT BN VFG PRWD HO TITE SM DIRTY W/ TR STY 0.0. SS. LT CY SM WHT LT TITE SL CALC TR ST S. DT GY THE LT BN

LINGELBACK # 3

RECEIVED FEB 13 1970

WORKOVER REPORT

- 1-23-70 Start m.i. and r.u. Colorado Well Service.
- 1-24-70 Leave Vernal 7:25 A.M. on location @ 7:55 A.M. Colorado Well Service crew on location, Dalbo water truck on location, C. J. Hart truck on location with CACL. 8-9 A.M. finish rigging up and start mixing CACL. 9-3:30 P.M. mix 140 bbls 10.2 #/gal.
 - 3:30-4:30 P.M. kill well w/115 bbls CACL water (calculated capacity to load well to 3500° is 51.16 bbls.)
 - 4:30-6:00 P.M. strip off head and install B.O. P.
- 1-25-70 On location @ 8:00 A.M. Colorado Well Service crew on location, well pressured up unloading heads of CACL H20 and dry gas, pump in approximately 10 bbls, ran out of CACL water did not have enough volume to kill well.

 Dalbo water truck on location w/load water @ II:30 A.M. C. J. Hart truck on location
 - Dalbo water truck on location w/load water @ II:30 A.M. C. J. Hart truck on location 11:30 A.M. w/load CACL.
 - 11:30 A.M. to 2:00 P.M. mix 150 bbls 10.2 #/gal.
 - 2:00-2:30 P.M. circulate and roll in tank w/guns to finish mix. S.i. well wait on daylight to kill and trip well.
- 1-26-70 On location 7:45 A.M. Colorado well service on location circulating in tank to condition CACL water.
 8:00-1030 A.M. kill well used 90 bbls CACL.
 - 10:45-11:50 A.M. POOH w/110 jts. tbg. 3429.35 ft. (used 60 bbls. CACL H20 to keep hole filled)
 12:00 -1:30 P.M. ran in w/Baker A.C. Tension Packer set Packer @ 3601 k.b. w/bottom
 - of Packer Bull plugged and 4 ft. machine perforated nipple 3601-3597° on 115 jts. 2 3/8° EUE 4.7# J-55 8 rd. tbg. Tbg. landed on 2 7/8° x 2 3/8° EUE swage nipple in well head flange.
 - 2:00-4:00 P.M. Strip off preventer and nipple up well head, fluid level dropping more slowly than on trip after setting Packer. S.i. for night.
- 1-27-70 On location @ 7:45 A.M. Colorado Well Service on location rigging up, swab, no flow on tubing, SIPT 300 p.s.i.
 - 8:45-9:30 A.M. swab well in.
 - 9:30-10:00 A.M. rig down, swab well, flowing heads of CACL H20 and gas
 - 10:30 A.M. Released rig to move to Gowe Govt.
 - 3:45 P.M. FPT 140 p.s.i., FPC 460 gage 1,790 MCF/D w/hvy spray of CACL water leave well on extended flow to clean up.
- 1-28-70 7:15 A.M. FPT 125 p.s.i., FPC 425 p.s.i. gage 1790 MCF/D still very wet but less than previous gage. Leave on ext. flow.
- 1-29-70 11:50 A.M. FPt 125 p.si., FPC 375 p.s.i. gage 1630 MCF/D w heavy spray of water fresh water is increasing as more ice is forming at end of flow line. Water rate is about the same as before rework. Shut in well
- 9:10 A.M. SIPT 925, SIPC 1340 p.s.i., open well, died in one minute to very weak blow, followed by large head of free water est. 2½ 3 bbls. followed by strong blow very wet gas.
 - 9:30 A.M. Steady spray of water w/gas leave on extended flow.
 - 11:30 P.M. FPT 125, FPC 375 p.s.i., 1,630 MCF/D w/ hvy spray of water . s.i. well

- 1-31-70 5:15 P.M. SIPT 975, SIPC 1325 p.s.i., open well to air, died two minute, fol. by large head of free water, est. 2½-4 bbls., fol. by heavy spray of free water in strong blow gas.
 9:15 P.M. FPT 125, FPC 400 p.s.i., gage 1790 MCF/D, very heavy spray of water,
- est., 75-100 B.W.P.D., 1v. well on ext. flow.

 7:15 A.M. FPT 125, FPC 375 p.s.i., gage 1600 MCF/D, no change in water production, est. 75-100 B.W.P.D., s.i. well.
- 2-2-70 SIPT 1325, SIPC 1350 p.s.i., m.i. w/work over unit.
- Finish r.u. Colorado Well Service, mix 100 sxs. CACL (150 bbls volume) kill well.

 Baker Packer would not release, working packer loose in 2 hrs. by driving down hole
 16 ft. POOH bull plug on packer had been in sand @ 3617°. Ran in w/Backer AC Tension
 Packer Conventional Set Packer @ 3598° prep to swab test perfs 3617°-18°.
- 2-4-70 Swab test perfs 3617-18* packer set conventional @ 3598* tested avgerage fill up 300* pr 30 min., no sustained gas flow. Water estimated 24 B.P.D. gas TSTM om 2* est. 60 MCF/D, kill well to unseat packer, reset packer conventional @ 3536* swab test 3552-53, 3572, 3576, 3582-83, 3588-89 and known zone 3617-18. Swab in @ 3:30 P.M. good blow gas, very wet 4:30 P.M. flowing to pit gage 500 MCF/D. 5:00 P.M. gage 500 MCF/D very wet. S.i. for night.
- Packer set conventional @ 3536 testing 3552-53, 3572, 3576, 3582-83, 3588-89 and retest 3617-18°. SIPT 14 hrs 1425 p.s.i. casing loaded above packer w/ CACL water. Open well @ 7 A.M. to air to clean up.
 8:45 A.M. gage 537 MCF/D w/est. 4.3 BWPH, water 10.1 #/gal.
 9:80 A.M. gage 572 MCF/D w/est. 103 BWPD water 8.6 # gal.
 9:30 A.M. gage 572 MCF/D w/est 103 BWPD kill well, POOH water 8.6 #/gal.
 Ran in w/Baker Packer Bull plugged, set macker @ 3536° prep to swab test above packer3512-13, 3468-69 and 3462-63. Start swabbing 1:30 P.M. rec. CACL water wt.
 10.1 #/gal swab rec.full tank 10.1 # /gal @ 4 P.M. turn to pit cents swabbbec. at 4:30 P.M. wt. 9.9 #/gal highly gas cut. Continue swabbing to 5 P.M. no flow, recovery 3 bbls. pr rum.
- 2-6-70 SIPT 100 SIPC 600 p.s.i. packer @ 3536 testing above packer 3512-13, 3468-69, and 3462-63. Open tubing died immediately, swab well 7:30 A.M. to 10 A.M. csg. 580 p.s.i. well flow gas 5 min. on swab run and die. Water sample wt. 8.6 #/gal. Continue swabbing well to 1:30 P.M. well will not produce over 15 min. behind swab. Water wt 8.6 #/gal released crew s.i. well. 8 P.M. SIPT 300 SIPC 900 p.s.i.
- Sipt 300 SIPC 980 p.s.i. swab 4 run well came in for 15 min. and died. Casing pressure drop from 800-360 p.s.i. water weight 8.9 #/gal. Packer @ 3536, testing 3 zones above packer 3512-13, 3468-69, 3462-63. Kill well and reset packer @ 3507 to test two upper zones 3468-69 and 3462-63, swab back and recovered load fld. at 3 P.M. Continue swabbing to pit recovery Highly gas cut calcum chloride water wt. decreased from 10.1 #/gal @ 3 P.M. to 9.2 gals @ 4 P.M. S.i. for night. No gas flow casing 200 p.s.i.
- Packer @ 3507 testing perfs 3468-69 and 3462-63 SIPT 100 SIPC 820 psi. 15 hr SI, Swab well 4 runs, well came in @ 8:10 A.M. flow to 8:25 A.M. died, csg. press decreased from 750 psi to 300 psi. Swab well recovered highly gas cut CACL water wt. 8.9 #/gal. Kill well reset packer @ 3601 nipple up well head and swab in well. Good blow gas very heavy spray of water too wet for gage. S.i. well released rig 3 P.M.

Note Tbg. Detail 115 joints 2 3/8" w/4" perf. nipple and AC Packer 3590

Add K.B. 11

3601 ft.

Form 9 / 331	U ED STATES		Form approved.	
(May 1963)		SUBMIT IN TRIP	Budget Bureau	
\	MENT OF THE INTE GEOLOGICAL SURVEY	KIOK verse side)	5. LEASE DESIGNATION AND U-026222	D SERIAL NO
SUNDRY NOT (Do not use this form for propos Use "APPLICA"	Sals to drill or to deepen or plu ATION FOR PERMIT—" for such		6. IF INDIAN, ALLOTTER OF	R TRIBE NAM
OIL GAS WELL OTHER			7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
Kenneth D. Lu	ff		Lingelbac	h
3. ADDRESS OF OPERATOR			9. WELL NO.	
520 Patterson	Building, Denver	, Colorado 80202	3	
4. LOCATION OF WELL (Report location of See also space 17 below.)	learly and in accordance with a	ny State requirements.*	10. FIELD AND POOL, OR W	ILDCAT
At surface			Horseshoe B	end
1527' FSL x 6	60' FEL (NE SE)		11. SEC., T., R., M., OR BLK. SURVEY OR AREA	. AND
			Sec. 20, T68,	
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH 1	3. STATE
Approved 12/15/69	4732*	KB	Uintah	Utah
16. Check Ap		Nature of Notice, Report, or O	other Data Ent report of:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WEL	L
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASIN	₹G
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL	CHANGE PLANS	(Other)	<u> </u>	
		(NOTE: Report results Completion or Recomple	of multiple completion on etion Report and Log form.)	Well
(Other)		ent details, and give pertinent dates,	including estimated date of	f starting a
	grations (Clearly state all perting on ally drilled, give subsurface lo	cations and measured and true vertica	i dopono ioi dia marioro da	a nonce per
(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPE proposed work. If well is direction nent to this work.) *	onally drilled, give subsurface lo	cations and measured and true vertica		w nonco por
(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPE proposed work. If well is directionent to this work.)*	grations (Clearly state all pertinonally drilled, give subsurface lo	cations and measured and true vertica		ia donos por

Load hole with water or mud, whichever is required to kill well. Spot 20 sack plug at 3450' and squeeze 5 sacks into perforations. Shoot 4 1/2" casing at free point estimated to be at approximately 2000'. When pipe is free, set 15 sacks cement in and out of stub. Pull casing and set 35 sacks cement in and out of surface casing set at 270'. Set 5 sacks cement at top of surface pipe with dry hole marker.

APPROVAL IS CONDITIONAL UPON UTILIZING PROVED BY DIVISION OF MUD BETWEEN ALL PLUGS; AND PLACING 80 GAS CONSERVATION OF THE CEMENT PLUG AT THE BASE OF THEOIL & GAS CONSERVATION SURFACE CASING, INSIDE PIPE.

BY Jaul M Burkel

Hove Welden Work	ay abone	dope on 7	126/72 & weeks	bl approd
8. I hereby certify that the foregoing is true and correct SIGNED	t	Operator	Wiel me 13	1/21/72
(This space for Federal or State office use)				
APPROVED BY CONDITIONS OF APPROVAL IF ANY:	TITLE	:	DATE	<u> </u>

y 1968)	UN SED STATES	SUBMIT IN TRIPL TE	Duage Date	au No. 42-R142
	MENT OF THE INTERI	OR verse side)	5. LEASE DESIGNATION	
	SEOLOGICAL SURVEY		U-0262	
SUNDRY NOTI	ICES AND REPORTS C	ON WELLS	0. 12 11.21.1, 11.22.2	
(Do not use this form for propose	als to drill or to deepen or plug by TION FOR PERMIT—" for such pr	ack to a different reservoir.		
Use Allinoa			7. UNIT AGREEMENT NA	AME
OIL GAS X OTHER				
WELL WELL OTHER NAME OF OPERATOR			8. FARM OR LEASE NAT	ME
Kenneth D. Lui	ee :		Lingelba	ch
ADDRESS OF OPERATOR	**		9. WELL NO.	
and the second s	Building, Denver,	Coloredo 80202	3	
LOCATION OF WELL (Report location cle	learly and in accordance with any	State requirements.*	10. FIELD AND POOL, O	R WILDCAT
See also space 17 below.) At surface			Horseshoe	Rend
15271 TST v 6/	60' FEL (NE SE)		11. SEC., T., R., M., OR	BLK. AND
1327 F30 X O	OO ILD (AL OL)		SURVEY OR AREA	
			Sec. 20, T	6S. RZLE
PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISE	
pproved 12/15/69	4732' KI		Uintah	Utah
Check Ap	propriate Box To Indicate N	ature of Notice, Keport, or t	Other Data	
NOTICE OF INTENT	TION TO:	SUBSEC	QUENT REPORT OF:	·
TEST WATER SHUT-OFF P	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING '	WELL
	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING C	ASING
	ABANDON*	SHOOTING OR ACIDIZING	ABANDONME	NT*
	CHANGE PLANS	(Other)		
(Other)		(Note: Report result	s of multiple completion pletion Report and Log fo	on Well
	don as follows:			
Load hole with 3450' and square free point is free, set and set 35 sec	h mud required to be at estimated to be at 15 sacks cement in cks cement in and c	perforations. Show approximately 200 and out of stub. out of surface cas	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270	ng e
Load hole with 3450' and square free point is free, set 1 and set 35 sacks constants.	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set hand set 35 sacks of the pit has be	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set hand set 35 sacks of the pit has be	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set hand set 35 sacks of the pit has be	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set hand set 35 sacks of the pit has be	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set hand set 35 sacks of the pit has be	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set hand set 35 sacks of the pit has be	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set hand set 35 sacks of the pit has be	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set and set 35 sac set 5 sacks of the pit has be marker erected.	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location.	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set and set 35 sac Set 5 sacks of The pit has be marker erected.	h mud required to be exce 5 sacks into p estimated to be at 15 sacks cement in and cement at top of sure een filled, location.	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	PA Datus
Load hole with 3450' and square free point is free, set and set 35 sac set 5 sacks of the pit has be marker erected.	h mud required to be eze 5 sacks into pestimated to be at 15 sacks cement in and cement at top of sureen filled, location.	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface cast	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	ng e
Load hole with 3450' and square free point is free, set and set 35 sac Set 5 sacks of The pit has be marker erected.	h mud required to be eze 5 sacks into p estimated to be at 15 sacks cement in and cement at top of sure een filled, location. Strue and correct	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface castrace pipe with dry on leveled and regular	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	PA Datus
Load hole with 3450' and square free point is free, set and set 35 sacks control of the pit has be marker erected. The pit has be marker erected.	h mud required to be eze 5 sacks into p estimated to be at 15 sacks cement in and cement at top of sure een filled, location. Strue and correct	perforations. Shoot approximately 200 and out of stub. out of stub. out of surface castrace pipe with dry on leveled and regular	ot 4 1/2" casi 00'. When pip Pull casing ing set at 270 hole marker.	PA Dotusi